



National Transportation Safety Board Aviation Accident Final Report

Location:	Wasilla, AK	Accident Number:	GAA16CA142
Date & Time:	03/01/2016, 1145 AKS	Registration:	N12BE
Aircraft:	MAULE M5	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The student pilot and his flight instructor conducted 6 takeoffs and landings in the tailwheel-equipped airplane. The student pilot then took off solo, flew in the traffic pattern, and during the landing he reported that as soon as my wheels hit the pavement it jerked hard to the right. The student pilot attempted to "straighten it out" but he reported that the airplane was going too fast so he applied power and attempted to take off. He then stated that the airplane "jumped me to the right of the runway," the airplane departed the runway to the right, the propeller impacted terrain, and the main landing gear collapsed under the fuselage. The airplane sustained substantial damage to the two right wing lift struts.

The student pilot verified that there were no preimpact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

As a safety recommendation, the student pilot stated "more practice" and "land on gravel."

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's failure to maintain directional control during the landing, which resulted in a runway excursion, and an impact with terrain.

Findings

Aircraft	Directional control - Not attained/maintained (Cause)
Personnel issues	Aircraft control - Student pilot (Cause)

Factual Information

History of Flight

Landing-flare/touchdown	Abnormal runway contact Attempted remediation/recovery
Landing-landing roll	Loss of control on ground (Defining event) Runway excursion Collision with terr/obj (non-CFIT)

Student Pilot Information

Certificate:	Student	Age:	21, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3	Last Medical Exam:	02/19/2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 22.2 hours (Total, all aircraft), 22.2 hours (Total, this make and model), 0.8 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	MAULE	Registration:	N12BE
Model/Series:	M5 235C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	7082C
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	AAIP	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	O-540 Series
Registered Owner:	John J. Minnick	Rated Power:	
Operator:	On file	Air Carrier Operating Certificate:	None

Meteorological Information and Flight Plan

Observation Facility, Elevation:	PAWS, 354 ft msl	Observation Time:	1936 UTC
Distance from Accident Site:	0 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:	305°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Clear	Temperature/Dew Point:	2° C / -10° C
Lowest Ceiling:	None	Visibility	10 Miles
Wind Speed/Gusts, Direction:	7 knots, 80°	Visibility (RVR):	
Altimeter Setting:	29.86 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Wasilla, AK (IYS)	Type of Flight Plan Filed:	None
Destination:	Wasilla, AK (IYS)	Type of Clearance:	None
Departure Time:	1100 AKS	Type of Airspace:	Class G

Airport Information

Airport:	WASILLA (IYS)	Runway Surface Type:	Asphalt
Airport Elevation:	353 ft	Runway Surface Condition:	Dry
Runway Used:	04	IFR Approach:	None
Runway Length/Width:	3700 ft / 75 ft	VFR Approach/Landing:	Stop and Go; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None		

Administrative Information

Investigator In Charge (IIC):	Michael J Hodges	Adopted Date:	05/03/2016
Additional Participating Persons:	Robert Young; FAA Anchorage FSDO; Wasilla, AK		
Publish Date:	05/03/2016		
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=92792		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.