



National Transportation Safety Board Aviation Accident Factual Report

Location:	COVINGTON, TN	Accident Number:	ATL95LA002
Date & Time:	10/01/1994, 1700 CDT	Registration:	N731PS
Aircraft:	CESSNA 188	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Serious
Flight Conducted Under:	Part 137: Agricultural		

On October 1, 1994, about 1700 central daylight time, a Cessna 188, N731PS, groundlooped during the landing roll at Covington, Tennessee. The airplane was operated by Baker Flying Service under the provisions of 14 CFR Part 137, and visual flight rules. Visual meteorological conditions prevailed. A flight plan was not filed for the aerial application flight. There were serious injuries to the commercial pilot, and the airplane was substantially damaged. Origination of the flight was Covington, Tennessee, about 1615.

The pilot reported that the airplane veered left during the landing and that the right rudder pedal and brake did not operate to oppose the divergent ground path. An inspector from the Tennessee Flight Standards District Office, Memphis, Tennessee, spoke with the pilot, and examined the accident site and the airplane, after the accident. He reported that the pilot said he was attempting to land on the runway, and overshot it. The airplane landed in the grass beside the runway. Tire tracks showed a normal landing roll, until about the last 700 feet where the tracks showed the airplane veered left, then entered a skid, breaking off the right main landing gear at the attachment point. The right wing then, struck the ground. According to the inspector, the rudder pedal, rudder cable, and rudder functioned. The brake pad did not exhibit excessive wear and the hydraulic line did not exhibit any pre-impact failure.

Pilot Information

Certificate:	Airline Transport; Commercial; Foreign; Student	Age:	47, Male
Airplane Rating(s):	None; Single-engine Land; Single-engine Sea	Seat Occupied:	Center
Other Aircraft Rating(s):	Airship; None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	Helicopter; None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	12/16/1993
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	3696 hours (Total, all aircraft), 1627 hours (Total, this make and model), 200 hours (Last 90 days, all aircraft), 80 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N731PS
Model/Series:	188 188	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Restricted; Normal; Transport	Serial Number:	18803053
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	03/17/1994, Annual	Certified Max Gross Wt.:	4000 lbs
Time Since Last Inspection:	242 Hours	Engines:	1 Reciprocating
Airframe Total Time:	4551 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Not installed	Engine Model/Series:	IO-520-D(26)
Registered Owner:	BEN BAKER	Rated Power:	300 hp
Operator:	BAKER FLYING SERVICE	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	ZEFG

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	NQA, 320 ft msl	Distance from Accident Site:	19 Nautical Miles
Observation Time:	1650 CDT	Direction from Accident Site:	210°
Lowest Cloud Condition:	Scattered / 10000 ft agl	Visibility	7 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	30° C / 15° C
Precipitation and Obscuration:			
Departure Point:	(M04)	Type of Flight Plan Filed:	None
Destination:	, TN (M04)	Type of Clearance:	IFR; None;
Departure Time:	1615 CDT	Type of Airspace:	Class G

Airport Information

Airport:	COVINGTON MUNICIPAL (M04)	Runway Surface Type:	Asphalt
Airport Elevation:	300 ft	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None; Practice
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	PRESTON E HICKS,
Additional Participating Persons:	GEARY HURST; MEMPHIS, TN
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .