



National Transportation Safety Board Aviation Accident Factual Report

Location:	PAYSON, AZ	Accident Number:	LAX95LA235
Date & Time:	07/01/1995, 1435 MST	Registration:	N2820Z
Aircraft:	PIPER PA-22-160	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

On July 1, 1995, at 1435 hours mountain standard time, a Piper PA-22-160, N2820Z, collided with trees during a forced landing following takeoff at Payson, Arizona. The forced landing was precipitated by a loss of engine power in the takeoff initial climb. The aircraft was owned and operated by the pilot, and was beginning a personal cross-country flight to Glendale, Arizona. Visual meteorological conditions prevailed at the time. The aircraft sustained substantial damage. The certificated private pilot and his one passenger sustained minor injuries. The flight was originating at the time of the accident.

The pilot reported that he purchased 20 gallons of fuel from the airport prior to departure. Responding fire department personnel stated that they turned off the fuel valve to control a fuel line leak after the accident.

An FAA inspector from the Scottsdale, Arizona, Flight Standards District Office examined the aircraft and reported finding no discrepancies. Fuel samples from the aircraft tanks and carburetor, and from the airport fuel truck used to refuel the aircraft, were taken for laboratory analysis. According to the laboratory report, the fuel samples tested were consistent with aviation gasoline. No significant water or other contaminants were found.

Pilot Information

Certificate:	Private	Age:	49, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	11/21/1994
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	2000 hours (Total, all aircraft), 600 hours (Total, this make and model), 2000 hours (Pilot In Command, all aircraft), 80 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N2820Z
Model/Series:	PA-22-160 PA-22-160	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	22-6813
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-320-B2B
Registered Owner:	STEVE K. BEATTY	Rated Power:	160 hp
Operator:	STEVE K. BEATTY	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	E69, 5157 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	1305 MST	Direction from Accident Site:	60°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	30 Miles
Lowest Ceiling:	Broken / 6000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	13 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	28° C / 10° C
Precipitation and Obscuration:			
Departure Point:	(E69)	Type of Flight Plan Filed:	None
Destination:	GLENDALE, AZ (GEU)	Type of Clearance:	None
Departure Time:	0000	Type of Airspace:	Class E

Airport Information

Airport:	PAYSON (E69)	Runway Surface Type:	Asphalt
Airport Elevation:	5157 ft	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	5504 ft / 75 ft	VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JEFF RICH
Additional Participating Persons:	BRUCE SMITH; SCOTTSDALE, AZ
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .