



National Transportation Safety Board Aviation Accident Factual Report

Location:	FRANKLIN, LA	Accident Number:	FTW96LA285
Date & Time:	07/01/1996, 0930 CDT	Registration:	N14637
Aircraft:	Hiller UH12	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None

Flight Conducted Under: Part 91: General Aviation - Business

On July 1, 1996, at 0930 central daylight time, a Hiller UH12E helicopter, N14637, was substantially damaged while executing a precautionary landing following a partial loss of engine power near Franklin, Louisiana. The helicopter, owned and operated by a private owner, was being operated under Title 14 CFR Part 91. Visual meteorological conditions prevailed and a flight plan was not filed. The commercial pilot, sole occupant of the aircraft, was not injured. The local business flight originated from Patterson, Louisiana, at 0815.

During personal interviews, conducted by the FAA inspector, the pilot reported that he heard a "bang" and the helicopter engine started "running rough" while the helicopter was operating at about 100 feet AGL en route between Patterson and Franklin. The pilot further stated that he elected to execute a precautionary landing to "investigate the source of the engine problems."

The pilot further stated that during the precautionary landing the "rotor RPM started to bleed and sufficient RPM could not be maintained for a successful landing." During the low rotor RPM landing touchdown to a muddy grass area, the front cross tube collapsed and the aft skid settled into the mud.

Examination of the airframe revealed that the tailboom, tailrotor gearbox, and a portion of the vertical stabilizer were severed from the helicopter as result of impact with the main rotor blades. The reason for the partial loss of engine power could not be determined.

The pilot did not complete any of the several Pilot/Operator Reports (NTSB Form 6120.1/2) that were mailed to him.

Pilot Information

Certificate:	Commercial	Age:	, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	3500 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hiller	Registration:	N14637
Model/Series:	UH12 UH12	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	1577
Landing Gear Type:	Skid	Seats:	
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	VO-540
Registered Owner:	DEWAYNE C. DAVIS	Rated Power:	225 hp
Operator:	DEWAYNE C. DAVIS	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	PATTERSON, LA (PTN)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	0915 CDT	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JOYCE M SMITH
Additional Participating Persons:	LAMONT WILLIFORD; BATON ROUGE, LA
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .