



National Transportation Safety Board Aviation Accident Factual Report

Location:	LUMBERTON, NC	Accident Number:	ATL91LA048
Date & Time:	02/02/1991, 2208 EST	Registration:	N4749P
Aircraft:	PIPER PA-23-250	Aircraft Damage:	None
Defining Event:		Injuries:	1 Fatal
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Flight Instructor; Commercial	Age:	66, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	Yes
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	08/01/1990
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	20000 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N4749P
Model/Series:	PA-23-250 PA-23-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	27-287
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:	0 Hours	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated	Engine Model/Series:	O-520
Registered Owner:		Rated Power:	250 hp
Operator:	HESTER, HARRY	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night/Dark
Observation Facility, Elevation:	FAY, 190 ft msl	Distance from Accident Site:	30 Nautical Miles
Observation Time:	2227 EST	Direction from Accident Site:	15°
Lowest Cloud Condition:	Scattered / 5000 ft agl	Visibility	7 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:			
Departure Point:	ORLANDO, FL (ORL)	Type of Flight Plan Filed:	VFR
Destination:	LUMBERTON, NC (LBT)	Type of Clearance:	None
Departure Time:	1806 EST	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	None
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC): Phillip Powell

Additional Participating Persons: LARRY LAMBERT; RALEIGH, NC

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.