



National Transportation Safety Board Aviation Accident Final Report

Location:	LEE VINING, CA	Accident Number:	LAX91LA154
Date & Time:	04/01/1991, 2100 PST	Registration:	N1941Y
Aircraft:	MOONEY M-20E	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	1 Fatal
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

THE CERTIFICATED PRIVATE PILOT WAS ON A CROSS COUNTRY FLIGHT THAT BEGAN AT ABOUT 0830 HOURS AND WAS PLANNED TO COVER ABOUT 1,300 NAUTICAL MILES. THE PILOT DEPARTED HIS LAST FUEL STOP AT ABOUT 2000 HOURS WHERE A WITNESS REPORTED THAT THE PILOT APPEARED FATIGUED. THE ROUTE OF FLIGHT WAS OVER HIGH MOUNTAINOUS TERRAIN THAT HAD A MINIMUM FLIGHT ELEVATION OF 13,500 FEET. AN EMERGENCY LOCATOR TRANSMITTER SIGNAL WAS RECEIVED AT 0024 HOURS, LOCATED 105 MILES WEST OF THE LAST DEPARTURE AIRPORT. THE AIRPLANE WAS LOCATED BY SEARCH PERSONNEL AT 11,000 FEET AND HAD IMPACTED A MOUNTAIN SIDE IN A REMOTE AREA OF DEEP SNOW. AT THE ACCIDENT LOCATION, THE AIRPLANE WAS ABOUT 1,000 FEET BELOW THE MOUNTAIN RIDGE LINE. THE TIME AND LOCATION OF THE ACCIDENT PLACED THE AIRPLANE IN AN AREA THAT DID NOT HAVE ANY GROUND OR MOON ILLUMINATION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:
THE FAILURE OF THE PILOT TO MAINTAIN ADEQUATE ALTITUDE TO CLEAR MOUNTAINOUS TERRAIN. CONTRIBUTING TO THE ACCIDENT WAS PILOT FATIGUE DUE TO A LENGTHY CROSS COUNTRY FLIGHT.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: CRUISE - NORMAL

Findings

1. TERRAIN CONDITION - SNOW COVERED
2. (C) PROPER ALTITUDE - NOT ATTAINED - PILOT IN COMMAND
3. (F) VISUAL LOOKOUT - NOT MAINTAINED - PILOT IN COMMAND
4. (F) FATIGUE(FLIGHT SCHEDULE) - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	46, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	12/11/1991
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	303 hours (Total, all aircraft), 154 hours (Total, this make and model), 175 hours (Pilot In Command, all aircraft), 44 hours (Last 90 days, all aircraft), 21 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY	Registration:	N1941Y
Model/Series:	M-20E M-20E	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	248
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	01/02/2000, Annual	Certified Max Gross Wt.:	2575 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	IO-360-AIA
Registered Owner:	ALAN D. MC DONALD	Rated Power:	200 hp
Operator:	ALAN D. MC DONALD	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night/Dark
Observation Facility, Elevation:	MCE, 153 ft msl	Distance from Accident Site:	70 Nautical Miles
Observation Time:	2046 PST	Direction from Accident Site:	220°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	20 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	11° C / 8° C
Precipitation and Obscuration:			
Departure Point:	TONOPAH, NV (THP)	Type of Flight Plan Filed:	None
Destination:	STOCKTON, CA (SCK)	Type of Clearance:	VFR
Departure Time:	2000 PST	Type of Airspace:	Special

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Scott Erickson	Report Date:	05/27/1993
Additional Participating Persons:	GEORGE EICHER; RENO, NV		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinquiry@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).