



National Transportation Safety Board Aviation Accident Factual Report

Location:	LAKE HAVASU, AZ	Accident Number:	LAX90FA235
Date & Time:	07/01/1990, 1820 MST	Registration:	N2307Y
Aircraft:	CESSNA 177	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	3 Fatal
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Private	Age:	25, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	09/01/1988
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	129 hours (Total, all aircraft), 33 hours (Total, this make and model), 91 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N2307Y
Model/Series:	177 177	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	17700107
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2350 lbs
Time Since Last Inspection:	0 Hours	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-320-E2D
Registered Owner:	REX H BURRESON	Rated Power:	150 hp
Operator:	BURRESON, REX H.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	EED, 990 ft msl	Distance from Accident Site:	20 Nautical Miles
Observation Time:	1600 PDT	Direction from Accident Site:	310°
Lowest Cloud Condition:	Scattered / 16000 ft agl	Visibility	35 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	48° C / -18° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:	PALM SPRINGS, CA (PSP)	Type of Clearance:	None
Departure Time:	1820 MST	Type of Airspace:	

Airport Information

Airport:	LAKE HAVASU (LHV)	Runway Surface Type:	Asphalt
Airport Elevation:	483 ft	Runway Surface Condition:	Dry
Runway Used:	5	IFR Approach:	None
Runway Length/Width:	6167 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	2 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	GEORGE E PETERSON
Additional Participating Persons:	CHARLES R LITTLE; WILLIAMSPORT, PA SANDY GARCIA; WICHITA, KS
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .