



National Transportation Safety Board Aviation Accident Factual Report

Location:	MUSKEGON, MI	Accident Number:	CHI91LA037
Date & Time:	12/02/1990, 1205 EST	Registration:	N7321B
Aircraft:	CESSNA 152	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None

Flight Conducted Under: Part 91: General Aviation - Instructional

Pilot Information

Certificate:	Student	Age:	24, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	08/07/1990
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	17 hours (Total, all aircraft), 16 hours (Total, this make and model), 2 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N7321B
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	1520743
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	0 Hours	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	O-235-L2C
Registered Owner:	UNKNOWN	Rated Power:	110 hp
Operator:	TULIP CITY AIR SERVICE, INC.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	MKG, 628 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1208 EST	Direction from Accident Site:	0°
Lowest Cloud Condition:	Thin Broken / 25000 ft agl	Visibility	15 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:			
Departure Point:	(MKG)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1050 EST	Type of Airspace:	

Airport Information

Airport:	MUSKEGON (MKG)	Runway Surface Type:	Asphalt
Airport Elevation:	628 ft	Runway Surface Condition:	Dry
Runway Used:	6	IFR Approach:	None
Runway Length/Width:	6501 ft / 150 ft	VFR Approach/Landing:	Touch and Go

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JOHN R HRUBAN
Additional Participating Persons:	WILLIAM NAYMICH
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .