



National Transportation Safety Board Aviation Accident Data Summary

Location:	OAKDALE, CA	Accident Number:	LAX87FA286
Date & Time:	08/01/1987, 0015 PDT	Registration:	N2098B
Aircraft:	LUSCOMBE 8A	Injuries:	2 Fatal
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

THE PLT & HIS PLT-RATED WIFE (FLYING IN THEIR LUSCOMBE) & ANOTHER COUPLE (IN A RENTED MOONEY) HAD DINNER & DRANK WINE. BY ABOUT 0015 THE COUPLES HAD TAKEN OFF IN THEIR RESPECTIVE ACFT FOR A RETURN FLT HOME AND THEY HAD EACH OTHER IN SIGHT. THE COUPLE IN THE MOONEY STATED THAT WHILE CRUISING AT 6,500 FEET MSL (& ON A FEDERAL AIRWAY) THE PLT IN THE LUSCOMBE TRANSMITTED 'I'LL SHOW YOU SOMETHING. I'M GOING TO DO A VERTICAL 360. WATCH THIS.' THE MOONEY PLT OBSERVED THE LUSCOMBE DESCEND SLIGHTLY & THEN COMMENCE A CLIMB. THEREAFTER, CONTACT WAS LOST. THE LUSCOMBE WRECKAGE WAS SUBSEQUENTLY FOUND IN NUMEROUS PIECES DISTRIBUTED OVER 3/4-MI. EXAM OF THE ACFT STRUCTURE INCLUDING WING SPARS REVEALED SEVERE CORROSION. NO EVIDENCE OF THE ACFT HAVING A CURRENT ANNUAL INSPECTION WAS FOUND. TOXICOLOGICAL TESTS REVEALED ETHANOL LEVELS OF .02 PERCENT AND .08 PERCENT FOR THE PLT AND HIS WIFE RESPECTIVELY.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ABRUPT MANEUVER
Phase of Operation: MANEUVERING

Findings

1. (F) JUDGMENT - POOR - PILOT IN COMMAND
 2. (C) AEROBATICS - INTENTIONAL - PILOT IN COMMAND
 3. (C) FLIGHT CONTROLS - IMPROPER USE OF - PILOT IN COMMAND
-

Occurrence #2: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: MANEUVERING

Findings

4. (F) MAINTENANCE, ANNUAL INSPECTION - NOT PERFORMED - PILOT IN COMMAND
5. (F) MAINTENANCE, COMPLIANCE WITH AD - NOT PERFORMED - PILOT IN COMMAND
6. (C) STABILIZER - FAILURE, TOTAL
7. (C) WING, SPAR - FAILURE, TOTAL
8. (C) WING, SPAR - CORRODED
9. (C) WING, WING ATTACHMENT FITTING - OVERLOAD

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Pilot Information

Certificate:	Private	Age:	49
Airplane Rating(s):	Single-engine Land	Instrument Rating(s):	None
Other Aircraft Rating(s):	None	Instructor Rating(s):	None
Flight Time:	2100 hours (Total, all aircraft), 2100 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	LUSCOMBE	Registration:	N2098B
Model/Series:	8A 8A	Engines:	1 Reciprocating
Operator:	FRANCIS & MELISSA MINGS	Engine Manufacturer:	LYCOMING
Operating Certificate(s) Held:	None	Engine Model/Series:	O-320
Flight Conducted Under:	Part 91: General Aviation - Personal		

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night/Bright
Observation Facility, Elevation:	, 0 ft msl	Weather Information Source:	Witness
Lowest Ceiling:	None / 0 ft agl	Wind Speed/Gusts, Direction:	/ ,
Temperature:		Visibility	50 Miles
Precipitation and Obscuration:			
Departure Point:	COLUMBIA, CA (022)	Destination:	HAYWARD, CA (HWD)

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Latitude, Longitude:			

Administrative Information

Investigator In Charge (IIC): WAYNE POLLACK Adopted Date: 06/16/1989

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.