



National Transportation Safety Board Aviation Accident Factual Report

Location:	DRAYTON PLAINES, MI	Accident Number:	CHI86FA094B
Date & Time:	03/01/1986, 1612 EST	Registration:	N48003
Aircraft:	CESSNA 172M	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	1 Fatal, 1 Serious
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Private	Age:	39, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	02/21/1984
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	261 hours (Total, all aircraft), 261 hours (Total, this make and model), 230 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N48003
Model/Series:	172M 172M	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	17263886
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	01/06/1986, 100 Hour	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:	7 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1691 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-320-E2D
Registered Owner:	107TH FLYING CLUB	Rated Power:	150 hp
Operator:	107TH FLYING CLUB	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	PTK, 980 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	1615 EST	Direction from Accident Site:	92°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	Overcast / 4000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1430 EST	Type of Airspace:	Class D

Airport Information

Airport:	PONTIAC-OAKLAND (PTK)	Runway Surface Type:	Macadam
Airport Elevation:	980 ft	Runway Surface Condition:	Dry
Runway Used:	27R	IFR Approach:	None
Runway Length/Width:	3251 ft / 75 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal, 1 Serious	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ROBERT BENZON
Additional Participating Persons:	R SEBASTIAN; DES PLAINES, IL D F THOMAS; WASHINGTON, DC C FRANCIS; PONTIAC, MI R ALLCORN; BIRMINGHAM, MI
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .