



National Transportation Safety Board Aviation Accident Data Summary

Location:	WISDOM, MT	Accident Number:	DEN86LA086
Date & Time:	03/01/1986, 1100 MST	Registration:	N69043
Aircraft:	CESSNA 152	Injuries:	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

THE STUDENT PLT DEPARTED MINDEN, NV ON AN UNAUTHORIZED X-CO FLT THAT TERMINATED IN THE ACCIDENT AT WISDOM, MT. DURING THE LANDING ROLL AT AN ABANDONED ARPT AT WISDOM, THE NOSE OF THE ACFT DUG INTO THE SNOW COVERED RUNWAY AND THE ACFT NOSED OVER. THE PLT RECEIVED MINOR INJURIES.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE OVER
Phase of Operation: LANDING - ROLL

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND
2. (C) TERRAIN CONDITION - SNOW COVERED
3. (F) AIRPORT/FACILITIES - UNAPPROVED

Pilot Information

Certificate:	Student	Age:	50
Airplane Rating(s):	None	Instrument Rating(s):	None
Other Aircraft Rating(s):	None	Instructor Rating(s):	None
Flight Time:	66 hours (Total, all aircraft), 32 hours (Total, this make and model), 29 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N69043
Model/Series:	152 152	Engines:	1 Reciprocating
Operator:	JACK AND KAY HOUK	Engine Manufacturer:	LYCOMING
Operating Certificate(s) Held:	None	Engine Model/Series:	O-360-A1A
Flight Conducted Under:	Part 91: General Aviation - Personal		

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Weather Information Source:	Witness
Lowest Ceiling:	None / 0 ft agl	Wind Speed/Gusts, Direction:	/ ,
Temperature:		Visibility	15 Miles
Precipitation and Obscuration:			
Departure Point:	MINDEN, NV (415)	Destination:	WISDOM, MT (754)

Airport Information

Airport:	WISDOM (754)	Runway Surface Type:	Grass/turf
Runway Used:	1	Runway Surface Condition:	Snow-crusted
Runway Length/Width:	3400 ft / 75 ft		

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None

Latitude, Longitude:

Administrative Information

Investigator In Charge (IIC):	VERLIN B TRANTER	Adopted Date:	
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.