



National Transportation Safety Board Aviation Accident Factual Report

Location:	HASTINGS, FL	Accident Number:	MIA86LA140
Date & Time:	05/01/1986, 1730 EDT	Registration:	N1279S
Aircraft:	CESSNA 182P	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Business		

Pilot Information

Certificate:	Private	Age:	47, Female
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	10/10/1984
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	256 hours (Total, all aircraft), 108 hours (Total, this make and model), 178 hours (Pilot In Command, all aircraft), 16 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N1279S
Model/Series:	182P 182P	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	18264847
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	04/01/1986, 100 Hour	Certified Max Gross Wt.:	2950 lbs
Time Since Last Inspection:	11 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1295 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	O-470-S
Registered Owner:		Rated Power:	230 hp
Operator:	RAYMOND LAMAR	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	CRG, 41 ft msl	Distance from Accident Site:	37 Nautical Miles
Observation Time:	1751 EDT	Direction from Accident Site:	182°
Lowest Cloud Condition:	Unknown / 25000 ft agl	Visibility	7 Miles
Lowest Ceiling:	Broken / 25000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	26° C / 14° C
Precipitation and Obscuration:			
Departure Point:	CRYSTAL SPRINGS, MS (MLL)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1312 CDT	Type of Airspace:	Class E

Airport Information

Airport:	HASTINGS INT'L (80J)	Runway Surface Type:	Grass/turf
Airport Elevation:	25 ft	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	2300 ft / 100 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JORGE A PRELLEZO
--------------------------------------	------------------

Additional Participating Persons:

Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .
------------------------------	--