



National Transportation Safety Board Aviation Accident Factual Report

Location:	BAKERSFIELD, CA	Accident Number:	LAX85LA161
Date & Time:	03/01/1985, 1015 PST	Registration:	N89716
Aircraft:	CESSNA 152	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None

Flight Conducted Under: Part 91: General Aviation - Instructional

Pilot Information

Certificate:	Student	Age:	42, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	06/29/1984
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	34 hours (Total, all aircraft), 34 hours (Total, this make and model), 9 hours (Pilot In Command, all aircraft), 11 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N89716
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	15282837
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	11/06/1984, 100 Hour	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	72 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1580 Hours	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-235-L2C
Registered Owner:	SIERRA FLITE SERVICE	Rated Power:	110 hp
Operator:	SIERRA FLITE SERVICE	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	BFL, 490 ft msl	Distance from Accident Site:	11 Nautical Miles
Observation Time:	0953 PST	Direction from Accident Site:	152°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	6 Miles
Lowest Ceiling:	Broken / 25000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	18° C / 6° C
Precipitation and Obscuration:			
Departure Point:	BAKERSFIELD, CA (BFL)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	0945 PST	Type of Airspace:	Class G

Airport Information

Airport:	POSO KERN COUNTY (L73)	Runway Surface Type:	Asphalt
Airport Elevation:	635 ft	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	3000 ft / 60 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JEFF RICH
Additional Participating Persons:	LARRY R PERKINS; FRESNO, CA
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .