



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	LACON, IL	<b>Accident Number:</b>	CHI84LA101
<b>Date &amp; Time:</b>	02/01/1984, 1630 CST	<b>Registration:</b>	N91469
<b>Aircraft:</b>	PIPER PA38-112	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None

**Flight Conducted Under:** Part 91: General Aviation - Ferry

---

## Pilot Information

---

<b>Certificate:</b>	Private	<b>Age:</b>	18, Female
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	05/23/1983
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	93 hours (Total, all aircraft), 24 hours (Total, this make and model), 49 hours (Pilot In Command, all aircraft), 20 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N91469
Model/Series:	PA38-112 PA38-112	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	38-82A0038
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	10/10/1983, Annual	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	95 Hours	Engines:	1 Reciprocating
Airframe Total Time:	595 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-235-L2C
Registered Owner:	MEAD RAYMOND CORP.	Rated Power:	112 hp
Operator:	MEAD RAYMOND CORP.	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	PIA, 660 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	1550 CST	Direction from Accident Site:	30°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	12 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	7° C / 2° C
Precipitation and Obscuration:			
Departure Point:	PEORIA, IL (PIA)	Type of Flight Plan Filed:	None
Destination:	LACON, IL (C75)	Type of Clearance:	None
Departure Time:	1610 CST	Type of Airspace:	Class G

## Airport Information

Airport:	LACON (C-75)	Runway Surface Type:	Asphalt
Airport Elevation:	554 ft	Runway Surface Condition:	Snow--dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	2200 ft / 50 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

## Administrative Information

Investigator In Charge (IIC):	EDWARD J MCAVOY
Additional Participating Persons:	C. E DOUGAN, SR.; SPRINGFIELD, IL R. E ATKINS; SPRINGFIELD, IL
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .