



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	STEVENSON, AL	<b>Accident Number:</b>	ATL82DA151
<b>Date &amp; Time:</b>	06/01/1982, 1720 CDT	<b>Registration:</b>	N28945
<b>Aircraft:</b>	PIPER PA-34-200T	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Business		

---

## Pilot Information

---

<b>Certificate:</b>	Private	<b>Age:</b>	32, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Unknown
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 3 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	09/15/1980
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	2313 hours (Total, all aircraft), 743 hours (Total, this make and model), 2213 hours (Pilot In Command, all aircraft), 108 hours (Last 90 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N28945
Model/Series:	PA-34-200T PA-34-200T	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	8070062
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	4000 lbs
Time Since Last Inspection:	83 Hours	Engines:	2 Reciprocating
Airframe Total Time:	881 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	TISO-360
Registered Owner:	ANDERSON CHEMICAL COMPANY	Rated Power:	200 hp
Operator:	ANDERSON CHEMICAL COMPANY	Operating Certificate(s) Held:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 4000 ft agl	Visibility	15 Miles
Lowest Ceiling:	Unknown / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	90° C / 0° C
Precipitation and Obscuration:			
Departure Point:	MACON, GA	Type of Flight Plan Filed:	None
Destination:	NASSAU, BAHAMAS	Type of Clearance:	None
Departure Time:	1730	Type of Airspace:	

## Airport Information

Airport:	BRIDGEPORT MUNICIPAL	Runway Surface Type:	Macadam
Airport Elevation:	0 ft	Runway Surface Condition:	Dry
Runway Used:	8	IFR Approach:	None
Runway Length/Width:	5000 ft / 150 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	

## Administrative Information

**Investigator In Charge (IIC):**

**Additional Participating Persons:**

**Investigation Docket:** NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.