



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	LOGAN, UT	<b>Accident Number:</b>	SEA92LA034
<b>Date &amp; Time:</b>	01/02/1992, 1610 MST	<b>Registration:</b>	N65505
<b>Aircraft:</b>	CESSNA 152	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None

**Flight Conducted Under:** Part 91: General Aviation - Instructional

---

## Pilot Information

---

<b>Certificate:</b>	Student	<b>Age:</b>	22, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Unknown
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--w/ waivers/lim.	<b>Last FAA Medical Exam:</b>	10/31/1991
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	24 hours (Total, all aircraft), 24 hours (Total, this make and model), 6 hours (Pilot In Command, all aircraft), 24 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N65505
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	15281592
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	0 Hours	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated	Engine Model/Series:	O-235-L2C
Registered Owner:		Rated Power:	110 hp
Operator:	LOGAN AIR SERVICE	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 3000 ft agl	Visibility	5 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	-1° C / -6° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1530 MST	Type of Airspace:	

## Airport Information

Airport:	LOGAN (LGU)	Runway Surface Type:	Asphalt
Airport Elevation:	4454 ft	Runway Surface Condition:	Dry
Runway Used:	35	IFR Approach:	None
Runway Length/Width:	5931 ft / 100 ft	VFR Approach/Landing:	Traffic Pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Debra J Eckrote
<b>Additional Participating Persons:</b>	DAVE RODDA; SALT LAKE CITY, UT
<b>Investigation Docket:</b>	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .