



National Transportation Safety Board Aviation Accident Factual Report

Location:	SALOME, AZ	Accident Number:	LAX92LA133
Date & Time:	03/01/1992, 1500 MST	Registration:	N550HZ
Aircraft:	HELIO HST-550A	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	2 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Airline Transport	Age:	25, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land; Single-engine Sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	05/14/1991
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1725 hours (Total, all aircraft), 72 hours (Total, this make and model), 1564 hours (Pilot In Command, all aircraft), 81 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	HELIO	Registration:	N550HZ
Model/Series:	HST-550A HST-550A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Experimental	Serial Number:	007
Landing Gear Type:	Tailwheel	Seats:	5
Date/Type of Last Inspection:	09/17/1991, 100 Hour	Certified Max Gross Wt.:	5100 lbs
Time Since Last Inspection:		Engines:	1 Turbo Prop
Airframe Total Time:		Engine Manufacturer:	P&W
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	PT6A-27
Registered Owner:	MAYTAG, DAVID D. JR.	Rated Power:	680 hp
Operator:	MAYTAG, DAVID D. JR.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	60 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	20 knots / 30 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18° C
Precipitation and Obscuration:			
Departure Point:	PRESCOTT, AZ (PRC)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1415 MST	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC): Scott R Erickson

Additional Participating Persons: WAYNE MCKINNEY; SCOTTSDALE, AZ

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.