



National Transportation Safety Board Aviation Accident Factual Report

Location:	ANCHORAGE, AK	Accident Number:	ANC91DAG01
Date & Time:	03/01/1991, 1226 AST	Registration:	N2636A
Aircraft:	PIPER PA-20	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Student	Age:	37, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	10/24/1990
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	81 hours (Total, all aircraft), 80 hours (Total, this make and model), 30 hours (Pilot In Command, all aircraft), 32 hours (Last 90 days, all aircraft), 17 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N2636A
Model/Series:	PA-20 PA-20	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	20-948
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	06/14/1990, Annual	Certified Max Gross Wt.:	1800 lbs
Time Since Last Inspection:	103 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3907 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-320
Registered Owner:	HICKOK, BRUCE D.	Rated Power:	150 hp
Operator:	HICKOK, BRUCE D.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	90 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	0° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	1030 AST	Type of Airspace:	Class D

Airport Information

Airport:	LAKE HOOD STRIP (Z41)	Runway Surface Type:	Gravel
Airport Elevation:	73 ft	Runway Surface Condition:	Wet
Runway Used:	31	IFR Approach:	None
Runway Length/Width:	2200 ft / 80 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC): Harry C Gilson

Additional Participating Persons:

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.