



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	VILLE PLATTE, LA	<b>Accident Number:</b>	FTW90DRD07
<b>Date &amp; Time:</b>	05/02/1990, 1045 CDT	<b>Registration:</b>	N8938H
<b>Aircraft:</b>	GRUMMAN G-164A	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

---

## Pilot Information

---

<b>Certificate:</b>	Commercial	<b>Age:</b>	43, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Center
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	Airplane; Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	12/07/1989
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	11768 hours (Total, all aircraft), 5500 hours (Total, this make and model), 11511 hours (Pilot In Command, all aircraft), 150 hours (Last 90 days, all aircraft), 100 hours (Last 30 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	GRUMMAN	Registration:	N8938H
Model/Series:	G-164A G-164A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Restricted	Serial Number:	1366
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	12/17/1989, Annual	Certified Max Gross Wt.:	4500 lbs
Time Since Last Inspection:	280 Hours	Engines:	1 Reciprocating
Airframe Total Time:	6092 Hours	Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	R-1340-AN1
Registered Owner:	PATRICK AARON YOUNG	Rated Power:	600 hp
Operator:	PATRICK AARON YOUNG	Operating Certificate(s) Held:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 2500 ft agl	Visibility	7 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	29° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1040 CDT	Type of Airspace:	Class G

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

## Administrative Information

---

**Investigator In Charge (IIC):** HENRY J CHRISTIAN

**Additional Participating Persons:**

**Investigation Docket:** NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.