



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	SPRINGFIELD, KY	<b>Accident Number:</b>	ATL88LA071
<b>Date &amp; Time:</b>	01/02/1988, 1500 EST	<b>Registration:</b>	N2906X
<b>Aircraft:</b>	CESSNA 177	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Serious
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

---

## Pilot Information

---

<b>Certificate:</b>	Private	<b>Age:</b>	61, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--w/ waivers/lim.	<b>Last FAA Medical Exam:</b>	01/15/1986
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	880 hours (Total, all aircraft), 9 hours (Total, this make and model), 786 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N2906X
Model/Series:	177 177	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	17700306
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	09/23/1987, Annual	Certified Max Gross Wt.:	2275 lbs
Time Since Last Inspection:	9 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3740 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-320-E3D
Registered Owner:	JACK U. COLLEY	Rated Power:	150 hp
Operator:	JACK U. COLLEY	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	LEX, 980 ft msl	Distance from Accident Site:	38 Nautical Miles
Observation Time:	1450 EST	Direction from Accident Site:	45°
Lowest Cloud Condition:	Thin Broken / 25000 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	0° C / -15° C
Precipitation and Obscuration:			
Departure Point:	(612)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1500 EST	Type of Airspace:	Class G

## Airport Information

Airport:	LEBANON-SPRINGFIELD (612)	Runway Surface Type:	Asphalt
Airport Elevation:	855 ft	Runway Surface Condition:	Dry
Runway Used:	29	IFR Approach:	None
Runway Length/Width:	4000 ft / 75 ft	VFR Approach/Landing:	Forced Landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious	<b>Latitude, Longitude:</b>	

## Administrative Information

<b>Investigator In Charge (IIC):</b>	CHARLES T FOUTS
<b>Additional Participating Persons:</b>	PHILIP C MESSINA; LOUISVILLE, KY
<b>Investigation Docket:</b>	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .