



National Transportation Safety Board Aviation Accident Factual Report

Location:	LANCASTER, CA	Accident Number:	LAX88LA243
Date & Time:	07/01/1988, 0540 PDT	Registration:	N4179K
Aircraft:	RYAN NAVION	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Private	Age:	65, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	02/13/1987
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1200 hours (Total, all aircraft), 304 hours (Total, this make and model), 1200 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	RYAN	Registration:	N4179K
Model/Series:	NAVION NAVION	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	NAV-4-1179
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	08/14/1987, Annual	Certified Max Gross Wt.:	2750 lbs
Time Since Last Inspection:	40 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3024 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-470
Registered Owner:	BRYAN, PATRICK O.	Rated Power:	260 hp
Operator:	BRYAN, PATRICK O.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	5 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:	REDDING, CA (RDD)	Type of Clearance:	None
Departure Time:	0540 PDT	Type of Airspace:	Class E

Airport Information

Airport:	GENERAL WM J. FOX FIELD (WJF)	Runway Surface Type:	Asphalt
Airport Elevation:	2347 ft	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	5001 ft / 150 ft	VFR Approach/Landing:	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	DEBRA J ECKROTE
Additional Participating Persons:	BOB ROEHM; VAN NUYS, CA
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .