



National Transportation Safety Board Aviation Accident Factual Report

Location:	COOL, CA	Accident Number:	LAX89LA298
Date & Time:	09/01/1989, 1038 PDT	Registration:	N97628
Aircraft:	STINSON 108	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Pilot Information

Certificate:	Private	Age:	26, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	06/16/1989
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	305 hours (Total, all aircraft), 100 hours (Total, this make and model), 264 hours (Pilot In Command, all aircraft), 25 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	STINSON	Registration:	N97628
Model/Series:	108 108	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	108-628
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2365 lbs
Time Since Last Inspection:	15 Hours	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	FRANKLIN
ELT:	Installed, not activated	Engine Model/Series:	6A4-165
Registered Owner:	GARY A CASSEN	Rated Power:	165 hp
Operator:	CASSEN, GARY A.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	50 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27° C
Precipitation and Obscuration:			
Departure Point:	AUBURN, CA (AUN)	Type of Flight Plan Filed:	None
Destination:	GEORGETOWN, CA (Q61)	Type of Clearance:	None
Departure Time:	1030 PDT	Type of Airspace:	Class G

Airport Information

Airport:	AUBURN (001)	Runway Surface Type:	
Airport Elevation:	1520 ft	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	A. D LLORENTE
Additional Participating Persons:	DONALD J ENGLESMAN; SACRAMENTO, CA
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .