



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	AVA, MO	<b>Accident Number:</b>	MKC86LA078
<b>Date &amp; Time:</b>	04/02/1986, 1725 CST	<b>Registration:</b>	N80751
<b>Aircraft:</b>	CESSNA 172	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	3 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

---

## Pilot Information

---

<b>Certificate:</b>	Private	<b>Age:</b>	18, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	08/30/1986
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	191 hours (Total, all aircraft), 114 hours (Total, this make and model), 131 hours (Pilot In Command, all aircraft), 69 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N80751
Model/Series:	172 172	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	17266728
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	01/22/1986, 100 Hour	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:	94 Hours	Engines:	1 Reciprocating
Airframe Total Time:	5950 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-320-E2D
Registered Owner:		Rated Power:	150 hp
Operator:	SCHOOL OF THE OZARKS	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	15 Miles
Lowest Ceiling:	Broken / 4000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	21 °C
Precipitation and Obscuration:			
Departure Point:	POINT LOOKOUT, MO (PLK)	Type of Flight Plan Filed:	None
Destination:	AVA, MO (73K)	Type of Clearance:	None
Departure Time:	1700 CST	Type of Airspace:	Class G

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

## Administrative Information

**Investigator In Charge (IIC):** ROBERT D JOHNSON

**Additional Participating Persons:** R ROBINSON; KANSAS CITY, MO  
R STERNECKER; KANSAS CITY, MO

**Investigation Docket:** NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.