



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	ALBERT, KS	<b>Accident Number:</b>	MKC85FA120
<b>Date &amp; Time:</b>	06/01/1985, 1520 CDT	<b>Registration:</b>	N6426B
<b>Aircraft:</b>	CESSNA 152	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>		<b>Injuries:</b>	2 Fatal
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

---

## Pilot Information

---

<b>Certificate:</b>	Private	<b>Age:</b>	18, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	07/01/1983
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	68 hours (Total, all aircraft), 32 hours (Total, this make and model), 36 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N6426B
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Utility	Serial Number:	14283932
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	10/27/1984, 100 Hour	Certified Max Gross Wt.:	1500 lbs
Time Since Last Inspection:	52 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1255 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-235-L2C
Registered Owner:	ELLINGWOOD FLYING SERV. INC.	Rated Power:	110 hp
Operator:	ELLINGWOOD FLYING SERV. INC.	Operating Certificate(s) Held:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	RSL, 1363 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	1558 CDT	Direction from Accident Site:	195°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	15 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	340°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	34° C
Precipitation and Obscuration:			
Departure Point:	BELOIT, KS (K61)	Type of Flight Plan Filed:	None
Destination:	ELLINGWOOD, KS (1K6)	Type of Clearance:	None
Departure Time:	1445 CDT	Type of Airspace:	Class G

## Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Fatal	Latitude, Longitude:	

## Administrative Information

<b>Investigator In Charge (IIC):</b>	CLINT C THORPE
<b>Additional Participating Persons:</b>	MIKE MUCHARME; WICHITA, KS
<b>Investigation Docket:</b>	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .