



National Transportation Safety Board Aviation Accident Factual Report

Location:	Pierre, SD	Accident Number:	CHI01LA306
Date & Time:	09/02/2001, 1215 CDT	Registration:	N4215Y
Aircraft:	Bellanca 7GCBC	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

On September 2, 2001, about 1215 central daylight time, a Bellanca 7GCBC, N4215Y, owned and piloted by a private pilot, sustained substantial damage during a ground loop during landing on runway 13 (6,891 feet by 150 feet, asphalt) at the Pierre Regional Airport, Pierre, South Dakota. The 14 CFR Part 91 personal flight was operating in visual meteorological conditions and was not on a flight plan. The pilot, who was the sole occupant, was not injured. The local flight originated at 1115.

In his written statement, the pilot said that while performing a practice short field landing, a gust of wind, "...picked aircraft from runway - placing it about a 30 [degree] angle to [the] direction of travel - with addition of power and control inputs, I was not able to correct before returning to runway. Resultant ground loop damaged landing gear and wing...."

The weather reporting station located at the accident airport recorded the wind at 1153 as variable direction at 4 knots. No gusts were listed on the 1153 report.

Pilot Information

Certificate:	Private	Age:	51, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	12/04/1999
Occupational Pilot:		Last Flight Review or Equivalent:	09/18/2000
Flight Time:	425 hours (Total, all aircraft), 6 hours (Total, this make and model), 363 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Bellanca	Registration:	N4215Y
Model/Series:	7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	968-77
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	10/17/2000, Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	20 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1219 Hours as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-320-A2D
Registered Owner:	Kenneth L. McGirr	Rated Power:	150 hp
Operator:	Kenneth L. McGirr	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	PIR, 1742 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1153 CDT	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.74 inches Hg	Temperature/Dew Point:	34° C / 14° C
Precipitation and Obscuration:			
Departure Point:	Pierre, SD (PIR)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1115 CDT	Type of Airspace:	Class E

Airport Information

Airport:	PIERRE REGIONAL (PIR)	Runway Surface Type:	Asphalt
Airport Elevation:	1742 ft	Runway Surface Condition:	Dry
Runway Used:	13	IFR Approach:	None
Runway Length/Width:	6891 ft / 150 ft	VFR Approach/Landing:	Full Stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	John M Brannen
Additional Participating Persons:	Dan McKinney; FAA-Rapid City, SD-FSDO; Rapid City, SD
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .