



National Transportation Safety Board Aviation Accident Factual Report

Location:	GRIFFIN, GA	Accident Number:	ATL82DA062
Date & Time:	03/01/1982, 1500 EST	Registration:	N4732Y
Aircraft:	PIPER PA-25-235	Aircraft Damage:	Minor
Defining Event:		Injuries:	1 Fatal, 1 Minor, 1 None

Flight Conducted Under: Part 91: General Aviation -

Pilot Information

Certificate:	Commercial	Age:	61, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	05/01/1981
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	7400 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N4732Y
Model/Series:	PA-25-235 PA-25-235	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	25-4480
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:	0 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1282 Hours	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-540-B2B5
Registered Owner:	WEST BOLIVAR FLYING SERVICE	Rated Power:	235 hp
Operator:	GENE SCOTT	Operating Certificate(s) Held:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	0 Miles
Lowest Ceiling:	Unknown / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	40°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	/ 0°C
Precipitation and Obscuration:			
Departure Point:	GRIFFIN, GA (6A2)	Type of Flight Plan Filed:	None
Destination:	GRIFFIN, GA (6A2)	Type of Clearance:	None
Departure Time:	1450	Type of Airspace:	

Airport Information

Airport:	GRIFFIN SPALDING (6A2)	Runway Surface Type:	Grass/turf
Airport Elevation:	0 ft	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	
Runway Length/Width:	2300 ft / 300 ft	VFR Approach/Landing:	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	1 Fatal, 1 Minor	Aircraft Explosion:	None
Total Injuries:	1 Fatal, 1 Minor, 1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.