



National Transportation Safety Board Aviation Accident Final Report

Location:	WINTERS, CA	Accident Number:	LAX82DA126
Date & Time:	04/01/1982, 1515 PST	Registration:	N35919
Aircraft:	CESSNA 206-F	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

AFTER TAKEOFF AS THE AIRCRAFT CLIMBED THROUGH 550 FEET AGL THE ENGINE LOST POWER. THE PILOT ATTEMPTED TO TURN THE AIRCRAFT AROUND AND LAND ON A TAXIWAY BUT LANDED IN A SOFT AREA NEAR IT. THE NOSE GEAR COLLAPSED AND THE AIRCRAFT SLID ACROSS THE TAXIWAY AND CAME TO A STOP. INVESTIGATION REVEALED THE FUEL CAP ON THE RIGHT WING WAS NOT PROPERLY SECURED AND A CONSIDERABLE AMOUNT OF FUEL IN THE RIGHT FUEL TANK. IN ADDITION THE AIRCRAFT HAD SAT OUT IN SEVERAL SEVERE RAINSTORMS FOR OVER A PERIOD OF A MONTH.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL
Phase of Operation: CLIMB - TO CRUISE

Findings

1. (C) FUEL SYSTEM,CAP - LOOSE
2. (C) FLUID,FUEL - WATER
3. (C) PREFLIGHT PLANNING/PREPARATION - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING
Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: GEAR COLLAPSED
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

4. (F) TERRAIN CONDITION - SOFT
5. (F) LANDING GEAR,NOSE GEAR - OVERLOAD

Factual Information

Pilot Information

Certificate:	Flight Instructor; Commercial	Age:	48, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land; Single-engine Sea	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	Airplane Single-engine	Toxicology Performed:	
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	11/21/1981
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	17096 hours (Total, all aircraft), 516 hours (Total, this make and model), 9999 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N35919
Model/Series:	206-F 206-F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	U20602799
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	102 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1843 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	IO-520-F
Registered Owner:	HOWARD ZANDERS	Rated Power:	300 hp
Operator:	HOWARD ZANDERS	Operating Certificate(s) Held:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	Broken / 1500 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	60° C / 0° C
Precipitation and Obscuration:			
Departure Point:	WINTERS, CA (2Q3)	Type of Flight Plan Filed:	None
Destination:	SACRAMENTO, CA	Type of Clearance:	None
Departure Time:	1515	Type of Airspace:	

Airport Information

Airport:	YOLO COUNTY (2Q3)	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft	Runway Surface Condition:	
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	6000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Report Date:	04/01/1983
Additional Participating Persons:		
Publish Date:		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .	

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).