



National Transportation Safety Board Aviation Accident Factual Report

Location:	BRUNSWICK, GA	Accident Number:	MIA85LA108
Date & Time:	03/01/1985, 1840 EST	Registration:	N6429Y
Aircraft:	PIPER PA-23-250	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under: Part 135: Air Taxi & Commuter - Non-scheduled			

Pilot Information

Certificate:	Airline Transport; Flight Instructor; Commercial	Age:	42, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider; Helicopter	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	10/03/1984
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	7100 hours (Total, all aircraft), 3505 hours (Total, this make and model), 6800 hours (Pilot In Command, all aircraft), 424 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N6429Y
Model/Series:	PA-23-250 PA-23-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	274385
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:	21 Hours	Engines:	2 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-540
Registered Owner:	WILLIAM G. WALTON	Rated Power:	250 hp
Operator:	WILLIAM G. WALTON	Operating Certificate(s) Held:	Commuter Air Carrier (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	Condition of Light:	Dusk
Observation Facility, Elevation:	SAV, 50 ft msl	Distance from Accident Site:	75 Nautical Miles
Observation Time:	1800 EST	Direction from Accident Site:	185°
Lowest Cloud Condition:	Thin Broken / 400 ft agl	Visibility	1 Miles
Lowest Ceiling:	Overcast / 2000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	16° C / 14° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	IFR
Destination:	SAVANNAH, GA (SAV)	Type of Clearance:	IFR
Departure Time:	0000	Type of Airspace:	Class E

Airport Information

Airport:	GLYNCO JETPORT (BQK)	Runway Surface Type:	Asphalt
Airport Elevation:	26 ft	Runway Surface Condition:	Wet
Runway Used:	7	IFR Approach:	None
Runway Length/Width:	8000 ft / 200 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	BRUCE J HILL
Additional Participating Persons:	JOE POOLE; JACKSONVILLE, FL
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .