



National Transportation Safety Board Aviation Accident Factual Report

Location:	EAST HANOVER, NJ	Accident Number:	NYC82DA015
Date & Time:	01/01/1982, 1430 EST	Registration:	N7967Q
Aircraft:	CESSNA 401B	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General Aviation - Business		

Pilot Information

Certificate:	Airline Transport	Age:	58, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land; Single-engine Sea	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	12/24/1981
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	5800 hours (Total, all aircraft), 2000 hours (Total, this make and model), 5100 hours (Pilot In Command, all aircraft), 25 hours (Last 90 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N7967Q
Model/Series:	401B 401B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	401B0107
Landing Gear Type:	Retractable - Tricycle	Seats:	8
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	6300 lbs
Time Since Last Inspection:	25 Hours	Engines:	2 Reciprocating
Airframe Total Time:	1317 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	IO-520
Registered Owner:	MILLICOR CORP	Rated Power:	300 hp
Operator:	MILLICOR CORP	Operating Certificate(s) Held:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	4 Miles
Lowest Ceiling:	Unknown / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	40°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	/ 0° C
Precipitation and Obscuration:			
Departure Point:	WILMINGTON, NC	Type of Flight Plan Filed:	IFR
Destination:	CALDWELL, NJ	Type of Clearance:	
Departure Time:	0000	Type of Airspace:	

Airport Information

Airport:	HANOVER (N58)	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft	Runway Surface Condition:	Wet
Runway Used:	9	IFR Approach:	ILS
Runway Length/Width:	2000 ft / 40 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.